

SCANSELECT PROGRAMMING TO RUBY VERIFONE

#1 Enter/Exit



#4 1200 Baud Rate



#2 Load Defaults



#5 Expand UPCE



#3 Enable XON/XOFF



#6 Conv. UPCA to EAN13



#7 Transmit UPC Pref ID



#8 Enter/Exit

