


Gilbarco Passport - Metroset configuration

Please scan the codes in the numbered order.

1. Enter Program Mode



999999

6. Disable Interleaved 2 of 5




100105

2. Load RS232 Defaults




999980

7. Transmit lead zero on UPC-E




107513

3. Disable Code 39



100101

8. Expand UPC-E



107515

4. Disable Code 128



100103

9. Transmit UPC-E Check Digit



107516

5. Disable Codabar



100104

10. 1 Stop Bit




116014

Gilbarco Passport - Metroset configuration


Please scan the codes in the numbered order.

11. Even Parity




316025

12. Disable Line Feed



116602

13. Exit Program Mode



999999