


**MS7120 ORBIT SETUP SHEET  
VERIFONE RUBY**




METROLOGIC INSTRUMENTS  
1(800) ID-METRO

**MS7120 ORBIT SETUP SHEET  
ENTER PROGRAM MODE**




PAGE 1

**MS7120 ORBIT SETUP SHEET  
RECALL DEFAULTS**




PAGE 2

**MS7120 ORBIT SETUP SHEET  
BAUD RATE = 1200**




PAGE 3

**MS7120 ORBIT SETUP SHEET  
ENABLE XON/XOFF**



PAGE 4


**MS7120 ORBIT SETUP SHEET  
EXPAND UPC-E TO UPC-A**



PAGE 5

# MS7120 ORBIT SETUP SHEET

CONVERT UPC-A TO EAN-13



PAGE 6

# MS7120 ORBIT SETUP SHEET


PROGRAMMABLE PREFIX CHARACTER #!



PAGE 7

# MS7120 ORBIT SETUP SHEET


CODE BYTE = F



PAGE 8

# MS7120 ORBIT SETUP SHEET


CODE BYTE = F



PAGE 9

# MS7120 ORBIT SETUP SHEET


CODE BYTE = F



PAGE 10

# MS7120 ORBIT SETUP SHEET

EXIT PROGRAMMING MODE



PAGE 11